

DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@dhw.idaho.gov

March 31, 2010

MichaelDay, Administrator Independent Living Services-- Milclay PO Box 6395 Boise, Idaho 83711

RE: Independent Living Services Milclay, Provider #13G011

Dear Mr. Day:

This is to advise you of the findings of the Medicaid/Licensure Fire Life Safety Survey, which was concluded at Independent Living Services Milclay, on March 23, 2010.

Enclosed is a Statement of Deficiencies/Plan of Correction, Form CMS-2567, listing Medicaid deficiencies and a similar form listing State licensure deficiencies. In the spaces provided on the right side of each sheet, please provide a Plan of Correction. <u>It is important</u> that your Plan of Correction address each deficiency in the following manner:

- 1. What corrective action(s) will be accomplished for those individuals found to have been affected by the deficient practice;
- How you will identify other individuals having the potential to be affected by the same deficient practice and what corrective action(s) will be taken;
- What measures will be put in place or what systemic change you will make to ensure that the deficient practice does not recur;
- 4. How the corrective action(s) will be monitored to ensure the deficient practice will not recur, i.e., what quality assurance program will be put into place; and,
- 5. Include dates when corrective action will be completed. 42 CFR 488.28 states ordinarily a provider is expected to take the steps needed to achieve compliance

MichaelDay, Administrator March 30, 2010 Page 2 of 2

within 60 days of being notified of the deficiencies. Please keep this in mind when preparing your plan of correction. For corrective actions which require construction, competitive bidding, or other issues beyond the control of the facility, additional time may be granted.

Sign and date the form(s) in the space provided at the bottom of the first page.

After you have completed your Plan of Correction, return the original to this office by **April 13, 2010**, and keep a copy for your records.

Thank you for the courtesies extended to us during our visit. If you have any questions, please call or write this office at (208) 334-6626.

Sincerely,

ERIC MUNDELL

Health Facility Surveyor

Com Mundle

Fire Life Safety & Construction Program

EM/lj

Enclosure

### DEPARTMENT OF HEALTH AND HUMAN SERVICES

Printed: 03/26/2010 FORM APPROVED MB NO 0938-0391

CENTERS FOR MEDICARE & MEDICAID SERVICES OMB NO. 0938-0391 STATEMENT OF DEFICIENCIES (X2) MULTIPLE CONSTRUCTION (X1) PROVIDER/SUPPLIER/CLIA (X3) DATE SURVEY AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** COMPLETED A. BUILDING 02 B. WING 13G011 03/23/2010 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE **INDEPENDENT LIVING SERVICES - MILCLAY** 10528 MILCLAY STREET **BOISE, ID 83704** (X5) COMPLETION SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID ID PRÉFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) K 000 INITIAL COMMENTS K 000 The facility is a single story, type V (000) building built in October 1998. The facility is protected by an automatic fire sprinkler system in habitable spaces. There is a fire alarm/smoke detection system installed. Currently the building is licensed for 5 beds. The following deficiency was cited under applicable fire/life safety requirements set forth in RECEIVED the Life Safety Code, 2000 edition, Chapter 33, Existing Residential Board and Care Occupancy, Impractical Evacuation Capability and 42 CFR APR 0 6 2010 483,470 FACILITY STANDARDS The annual fire/life safety survey was conducted by: Eric Mundell REHS Health Facility Surveyor Facility Fire/Life Safety and Construction Program K0056 483.470(j)(1)(i) LIFE SAFETY CODE K0056 The REPLACE BY COM STANDARD **PROMPT** Where an automatic sprinkler system is installed, for either total or partial building coverage, the ADMINISTER WILL system is in accordance with Section 9.7, 33.2.3.5.2 and activates the fire alarm system in accordance with 33.2.3.4.1. The adequacy of the water supply is documented to the authority having jurisdiction. Exception No. 1: In prompt evacuation facilities, an automatic springer system in accordance with FARWAR TO LOEATH THY NFPA 13D, Standard for the Installation of PMBUM. LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE TITLE (X6) DATE 10 Aun Manger

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

Printed: 03/26/2010 FORM APPROVED OMB NO. 0938-0391

OLIVILIO I OIL MEDIOMICE	WIND OF WOLD		O1950 140. 0000 000
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 82	(X3) DATE SURVEY COMPLETED
	13G011	8. WING	03/23/2010

NAME OF PROVIDER OR SUPPLIER

INDEPENDENT LIVING SERVICES - MILCLAY

STREET ADDRESS, CITY, STATE, ZIP CODE

BOISE, ID 83704					
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
	Continued From page 1 Sprinkler Systems in One and two Family Dwellings and Manufactured Homes, is permitted. Automatic sprinklers are not required in closets not exceeding 24 sq. ft. and in bathrooms not exceeding 55 sq. ft., provided that such spaces are finished with lath and plaster or materials providing a 15 minute thermal barrier.  Exception No. 2: Not applicable  Exception No. 3: In prompt and slow evacuation capability facilities where an automatic sprinkler system is in accordance with NFPA 13, Standard for the Installation of Sprinkler Systems, automatic sprinklers are not required in closets not exceeding 24 sq. ft and in bathrooms not exceeding 55 sq. ft., provided that such spaces are finished with lath and plaster or material providing a 15 minute thermal barrier.  Exception No. 4: In prompt and slow evacuation capability facilities up to and including four stories in height, systems in accordance with NFPA 13R, Standard for the Installation of Sprinkler Systems in Residential Occupancies up to and Including Four Stories in Height, are permitted.  Exception No. 5: Not applicable  Exception No. 6: Initiation of the fire alarm system		CROSS-REFERENCED TO THE APPROPRIATE	DATE	
	is not required for existing installations in accordance with 33.2.3.5.5.  SLOW  Where an automatic sprinkler system is installed, for either total or partial building coverage, the system is in accordance with Section 9.7 and activates the fire alarm system in accordance with 33.2.3.4.1. The adequacy of the water supply is documented to the authority having jurisdiction.				

Printed: 03/26/2010 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION

(X3) DATE SURVEY COMPLETED

13G011

A. BUILDING B. WING \_

03/23/2010

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

### INDEPENDENT LIVING SERVICES - MILCLAY

	BOIS	E, ID 83/04		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K0056	Continued From page 2	K0056		
	Exception No. 1: Not Applicable			
	Exception No. 2: Not Applicable	THE PART OF THE PA		
	Exception No. 3: In prompt and slow evacuation capability facilities where an automatic sprinkler system is in accordance with NFPA 13, Standard for the Installation of Sprinkler Systems, automatic sprinklers are not required in closets not exceeding 24 sq. ft. and in bathrooms not exceeding 55 sq. ft., provided that such spaces are finished with lath and plaster or material providing a 15 minute thermal barrier.			
	Exception No. 4: In prompt and slow evacuation capability facilities up to and including four stories in height, systems in accordance with NFPA 13R Standard for the Installation of Sprinkler Systems in Residential Occupancies up to and Including Four Stories in Height, are permitted.	,		
	Exception No. 5: Not Applicable			
	Exception No. 6: Initiation of the fire alarm system is not required for existing installations in accordance with 33.2.3.5.5.			
	IMPRACTICAL Where an automatic sprinkler system is installed for either total or partial building coverage, the system is in accordance with Section 9.7 and activates the fire alarm system in accordance wit 33.2.3.4.1. The adequacy of the water supply is documented to the authority having jurisdiction, 33.2.3.5.2.	Not seasons.		
	Exception No. 1: Not Applicable.			
	Exception No. 2: In slow and impractical	L L		

Printed: 03/26/2010 FORM APPROVED OMB NO. 0938-0391

			<u> </u>
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	IDENTIFICATION NI IMPER-	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02	(X3) DATE SURVEY COMPLETED
	13G011	B. WING	03/23/2010

NAME OF PROVIDER OR SUPPLIER

INDEPENDENT LIVING SERVICES - MILCLAY

STREET ADDRESS, CITY, STATE, ZIP CODE

BOISE, ID 83704					
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K0056	continued From page 3 evacuation capability facilities, an automatic sprinkler system in accordance with NFPA 13D, Standard for the Installation of Sprinkler Systems in One and Two Family Dwellings and Manufactured Homes, with a 30 minute water supply, is permitted. All habitable areas and closets are sprinklered. Automatic sprinklers are not required in bathrooms not exceeding 55 sq. ft., provided that such spaces are finished with lath and plaster or materials providing a 15 minute thermal barrier.  Exception No. 3: Not Applicable.  Exception No. 4: Not Applicable.  Exception No. 5: In impractical evacuation capability facilities up to and including four stories in height, systems in accordance with NFPA 13R, Standard for the Installation of Sprinkler Systems in Residential Occupancies up to and Including Four Stories in Height, are permitted. All habitable areas and closets are sprinklered. Automatic sprinklers are not required in bathrooms not exceeding 55 sq. ft., provided that such spaces are finished with lath and plaster or materials providing a 15 minute thermal barrier.  Exception No. 6: Initiation of the fire alarm system is not required for existing installations in accordance with 33.2.3.5.5.	K0056			
	This Standard is not met as evidenced by: Based on observation, it was determined that the facility had not ensured that all automatic fire sprinkler heads were maintained as required for one of three common areas sampled. The census was five (5) at the time of the observation.	T CT			

Printed: 03/26/2010 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

A. BUILDING

B. WING

03/23/2010

NAME OF PROVIDER OR SUPPLIER

### INDEPENDENT LIVING SERVICES - MILCLAY

STREET ADDRESS, CITY, STATE, ZIP CODE

BOISE, ID 83704					
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K0056	Continued From page 4 The findings include:  Observation on March 23, 2010 at 10:45 a.m. disclosed that the sprinkler head in the laundry room area off the corridor was marked with a	K0056			
	white painted strip from a previous application of paint on the ceiling. The strip, easily missed, had not been addressed by the sprinkler contractor where the head would be replaced upon discovery of the painted condition. The condition was observed by staff at the time of the observation.			o principality.	
	NFPA 13-D code reference:  1-4* Maintenance. The owner is responsible for the condition of a sprinkler system and shall keep the system in normal operating condition.				
	A-1-4 The responsibility for properly maintaining a sprinkler system is that of the owner or manager, who should understand the sprinkler system operation. A minimum monthly maintenance program should include the following.  (1) Visual inspection of all sprinklers to ensure against obstruction of spray.  (2) Inspection of all valves to ensure that they are open.				
•	<ul> <li>(3) Testing of all waterflow devices.</li> <li>(4) Testing of the alarm system, where installed.</li> <li>NOTE: Where it appears likely that the test will result in a fire department response, notification to the fire department should be made prior to the test.</li> <li>(5) Operation of pumps, where employed. (See NFPA 20, Standard for the Installation of Stationary Pumps for Fire Protection.)</li> <li>(6) Checking of the pressure of air used with dry</li> </ul>				

Printed: 03/26/2010 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02	(X3) DATE SURVEY COMPLETED
	13G011	B. WING	03/23/2010

NAME OF PROVIDER OR SUPPLIER

### INDEPENDENT LIVING SERVICES - MILCLAY

STREET ADDRESS, CITY, STATE, ZIP CODE

BOISE, ID 83704					
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K0056	Continued From page 5 systems.  (7) Checking of water level in tanks.  (8) Special attention to ensure that sprinklers are not painted either at the time of installation or during subsequent redecoration. When sprinkler piping or areas next to sprinklers are being painted, the sprinklers should be protected by covering them with a bag, which should be removed immediately after painting is finished.	K0056			

PRINTED: 04/14/2010 FORM APPROVED Bureau of Facility Standards STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED 02 - ENTIRE STRUCTURE A. BUILDING B. WING 13G011 03/23/2010 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 10528 MILCLAY STREET INDEPENDENT LIVING SERVICES - MILCLAY **BOISE, ID 83704** SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5)(EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PRÉFIX PREFIX COMPLETE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG CROSS-REFERENCED TO THE APPROPRIATE DATE DEFICIENCY) M 000 16.03.11 Inital Comments M 000 The facility is a single story, type V (000) building built in October 1998. The facility is protected by an automatic fire sprinkler system in habitable spaces. There is a fire alarm/smoke detection system installed. Currently the building is licensed for 5 beds. The following deficiency was cited under applicable fire/life safety requirements set forth in the Life Safety Code, 2000 edition, Chapter 33, Existing Residential Board and Care Occupancy, Impractical Evacuation Capability and IDAPA 16.03.11 Rules Governing Intermediate Care Facilities for the Mentally Retarded (ICF-MR). The state deficiency was resultant of a federal tag citation. The annual fire/life safety survey was conducted by: Eric Mundell REHS Health Facility Surveyor Facility Fire/Life Safety and Construction Program MM309 16.03.11.110 Fire and Life Safety Standards MM309 Kefer to KOS6 Buildings on the premises used as facilities must meet all the requirements of local, state and national codes concerning fire and life safety standards that are applicable to ICF/MR facilities. This Rule is not met as evidenced by: Refer to CMS federal form 2567 and K tag K056

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

regarding fire sprinkler head maintenance.

TITLE

(X6) DATE